

HB Regional Hospital, **Hastings**

HBDHB DESCRIPTION - Helicopter Service HA15

2-S5000.00



INTRODUCTION:


Opus International Consultants Ltd has undertaken an 'Initial Evaluation Procedure' (IEP) of HBDHB Helicopter Service, HB Regional Hospital, Hastings. The evaluation was carried out in accordance with NZ Society of Earthquake Engineering (NZSEE) guidelines (2006). The process includes internal and external non-invasive visual inspections, and an estimation of %NBS using the IEP process. Previous assessments have been used for deriving the IEP's and the values derived from detailed assessments have been adopted. Serviceability Limit State assessments for IL 4 buildings are not included.

BUILDING DESCRIPTION:

Building Name:	Helicopter Service	Building Use:	Aircraft Hangar	
Design/Constructed/ Upgraded:	2000	Importance Level	4	
General Shape:	Rectangle	No. of Storeys:	1	
Longitudinal Lateral Load Resisting System:	Steel framing	Transverse Lateral Load Resisting System:	Steel portal frame	
Foundation System:	Concrete slab	Other Level Floor Systems:	N/A	
Roof System:	Steel framing with light steel cladding	Primary Cladding Type:	Profiled light steel	
Most Recent Previous Assessment:	Year: 2005 By: Holmes Consulting Group Assessment: Informal SPS 100%			
Other Comments:	IL4 SLS Assessment recommended			

INITIAL EVALUATION PROCEDURE:

Helicopter Service is assessed as 100% NBS when considered as an IL4 building.



	Longitudinal	Transverse	
Baseline %NBS	80	80	
Factors Influencing Baseline	-	-	
Critical Structural Weaknesses	-	-	
Modification Factors	1.25	1.25	
Influence on Modification Factor	Site specific seismic study. Adequate cross bracing. No CSW's		
%NBS	100% NBS	100% NBS	

Prepared by:	R Ferguson	Date:	10 October 2013
Reviewed by:	N Evans	CPEng No:	19656
Released by:	N Evans	Report Issue:	

Telephone: +64 6 835 5100 Facsimile: +64 6 835 0881 Website: www.opus.co.nz