



HB Regional Hospital, Hastings

HBDHB DESCRIPTION – Addiction Services HA52



2-\$5000.00

INTRODUCTION:


Opus International Consultants Ltd has undertaken an 'Initial Evaluation Procedure' (IEP) of HBDHB Addiction Services, HB Regional Hospital, Hastings. The evaluation was carried out in accordance with NZ Society of Earthquake Engineering (NZSEE) guidelines (2006). The process includes internal and external non-invasive visual inspections, and an estimation of %NBS using the IEP process. Previous assessments have been used for deriving the IEP's and the values derived from detailed assessments have been adopted. Serviceability Limit State assessments for IL 4 buildings are not included.

BUILDING DESCRIPTION:

Building Name:	Addiction Services	Building Use:	Medical Services
Design/Constructed/Upgraded:	1960	Importance Level	2
General Shape:	Rectangle	No. of Storeys:	1
Longitudinal Lateral Load Resisting System:	Internal concrete walls. External concrete frame with pential brick infills	Transverse Lateral Load Resisting System:	Concrete perimeter columns internal bracing walls
Foundation System:	Concrete ring beam or slab	Other Level Floor Systems:	N/A
Roof System:	Light steel roof	Primary Cladding Type:	Sheet material
Most Recent Previous Assessment:	Year: 2013 By: Opus Assessment: IEP 34% NBS (IL2)		
Other Comments:	2017 Opus Comprehensive ISA 50% NBS (IL2)		

INITIAL EVALUATION PROCEDURE:

Addiction Services is assessed as **50% NBS** when considered as an IL2 building.



	Longitudinal	Transverse
Baseline %NBS	-	-
Factors Influencing Baseline	-	-
Critical Structural Weaknesses	Exterior wall brickwork is a potential CSW-	Exterior wall brickwork is a potential CSW -
Modification Factors	-	-
Influence on Modification Factor	-	-
%NBS	50% NBS	100% NBS

Prepared by:	R Ferguson	Date:	17 August 2017
Reviewed by:	N Evans	CPEng No:	19656
Released by:	N Evans	Report Issue:	